





**Task Number:** TN-21384

**Reference No.:** CFR 84.180

**Test:** Inhalation Resistance Test

**STP No.:** 7

**Manufacturer:** Xiantao Zhongyi Safety Protection Products Co.,

**Item Tested:** ZYB-11

**Comments:**

Samples were tested on manometer 000285.

Was all equipment verified to be in calibration throughout all testing?	<input checked="" type="radio"/> Yes	<input type="radio"/> No
---	--------------------------------------	--------------------------

**Signature:**



**Date:** 3/20/2017

**Engineering Technician**



**Task Number:** TN-21384

**Reference No.:** CFR 84.181

**Test:** Sodium Chloride (NaCl) - N95

**STP No.:** 59

**Manufacturer:** Xiantao Zhongyi Safety Protection Products Co.,

**Item Tested:** ZYB-11

**Comments:**

Samples 1-10 were tested on TSI 8130 machine 000332 using timer 000213. Samples 11-15 were tested on TSI 8130 machine 000333. Samples 16-20 were tested on TSI 8130 machine 000334.

Was all equipment verified to be in calibration throughout all testing?

Yes

No

**Signature:**

*Nichole L. Petetta*

**Date:** 3/21/2017

**Engineering Technician**